

SONY

**Dictation Products
Service Bulletin**

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: BM-18, BM-560

No. 21

Subject: Servo IC Part Number Correction

Date: February 5, 1993

Symptom:
(**)

The part number listed in the Service Manual for the Servo IC is incorrect.


Solution:

Please correct your Service Manual as follows:

MODEL	IC REF.	DESCRIPTION / PART NUMBER	
		INCORRECT	CORRECT
BM-18	IC-101	LA5524M / 8-759-820-70	LA5524 / 8-759-801-19
BM-560	IC-301	LA5524M / 8-759-801-19	LA5524M / 8-759-820-70



LA5524M
(SURFACE MOUNT TYPE)
BM-540, BM-560



LA5524
(INSERTION TYPE)
BT-500, BM-18

Dictation
CSA-15