

<b>VESTEL ELEKTRONİK A.Ş.</b>	<b>CHANGE BULLETIN (TCN)</b>	<b>CHANGE NO: 028 REF NO :ÜDM-468</b>
-----------------------------------	----------------------------------	---

**AFFECTED MODELS: ALL 11AK19 MODELS WITH TDA9870A.**

**START DATE : 21/08/1998**

**REASONS OF CHANGE: “DEEP NOISE” PROBLEM IN TDA9870A.**

**OUT**

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11ST19	3621598701	TDA 9870A	IC301	1
2					
3					
4					
5					

**IN**

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11 <sup>S</sup> 19	3621598701	TDA 9870	IC301	1
2					
3					
4					
5					

PRODUCTION SUPPORT ENGINEER	PRODUCTION SUPPORT CHIEF	PRODUCTION SUPPORT MANAGER CELAL ÖZKUL