

VESTEL ELEKTRONİK A.Ş.	CHANGE BULLETIN (TCN)	CHANGE NO: 52 REF NO :UMB - 701
-----------------------------------	----------------------------------	--

AFFECTED MODELS: ALL MODELS WITH 11AK19 CHASSIS.

START DATE : 01.07.1999

REASONS OF CHANGE: TO IMPROVE TELETEXT AND SYNCRONIZATION PERFORMANCE.

NOTE 1: This SMD type resistor must be soldered between the Base and Collector pins of Q406 under the PCB.

NOTE 2: This resistor must be soldered between the collectors of Q408 and Q409 on the component side of the PCB.

OUT

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK19	30000558	RES SMD 1/10W 180R J	R465	1
2	11AK19	30000524	RES SMD 1/10W 150R J	R429	1
3	11AK19	30002583	JUMPER WIRE	J264	1
4	11AK19	30000668	RES SMD 1/10W 33K J	R556	1

IN

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK19	30000688	RES SMD 1/10W 390R J	R465	1
2	11AK19	30000626	RES SMD 1/10W 270R J	R429	1
3	11AK19	30000469	RES SMD 1/10W 1K J	J264	1
4	11AK19	30000475	RES SMD 1/10W 10K J	NOTE 1	1
5	11AK19	30000594	RES CF 1/4W 22K J	NOTE 2	1

PRODUCTION SUPPORT ENGINEER	PRODUCTION SUPPORT CHIEF	PRODUCTION SUPPORT MANAGER
YILDIRAY BAŞKURT		CELAL ÖZKUL