

**Model:** KV-13M10, KV-13TR28, KV-13TR29, KV-20M10, KV-20S10, KV-20S11, KV-20TS29, KV-27V20, KV-27V22, KV-27V25, KV-27V35, KV-32S22, KV-32S26, KV-32TW26, KV-32V26, KV-32V36, KV-32XBR48, KV-35S26, KV-35V35, KV-35V36, KV-35V45, KV-35V76, KV-35XBR48, KV-35XBR88

**No. 339R2**

**Subject:** New Tuner Replacement

**Date:** June 1, 1998

**Symptom:**  
**(1310)**

New replacement tuner has five ground lugs compared to four on the original tuner. Board does not have a hole to accommodate the fifth lug.

**Solution:**

When replacing the tuner with the new replacement tuner it will become necessary to remove the fifth lug, located in the middle of the tuner.

Description	Former Part Number	New Part Number
Tuner (BTF-WA401)	8-598-340-10	8-598-254-51
Tuner(BTF-WA402)	8-598-254-00	8-598-254-51
Tuner (BTF-WA403)	8-598-269-00	8-598-340-20
Tuner (BTF-WA404)	8-598-340-00	8-598-340-20

