

SONY

Video Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: SEE BELOW

No. 143R1

Subject: Switching Position Adjustment 2
(MA-62 Board)

Date: April 15, 1991

SLV-272UC/-353UC/-373UC/-555UC/-575UC/-676UC/-757UC/
-P33UC/-R5UC

This Service Bulletin Supersedes Service Bulletin No. 143

Symptom:
(**)

When turning Pot RV501, per service manual adjustment procedure, there is no change to the head switching position and the waveform on the oscilloscope remains the same.

Solution: If this symptom occurs, put the unit in manual tracking mode then continue with the adjustment.

VHS
CSV-2

Reference:

PRINTED IN U.S.A.
CSV-2491-2