

SONY

Video Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: SLV-353UC/555UC/757UC

No. 147

Subject: New Part Number For System Control
IC501

Date: March 29, 1991

Symptom:
(**)

The new part number for the improved System Control IC501
is:

Solution:

Solution:

| Ref. No. | Description | | Part Number | |
|----------|----------------|----------------|--------------|--------------|
| | Former | New | Former | New |
| IC501 | CXP-80116-160Q | CXP-80116-166Q | 8-752-811-87 | 8-752-813-72 |
| | CXP-80116-161Q | | 8-752-811-88 | |
| | CXP-80116-158Q | | 8-752-811-45 | |

Note: If the unit has a "GM-20" Board, it should be
removed when the new IC is installed.

VHS
CSV-2