

1996

TOSHIBA AMERICA CONSUMER PRODUCTS, INC.

Date: 3/20/96

TECHNICAL BULLETIN

No. VCR9601

Product: VCRCombo

Countries affected: USA, CANADA

MODEL	VCR COMBO	
USA	CV25E48	CV27E48
CANADA	CV25E48	CV27E48

NOTE: The information in this bulletin should only be used if you encounter the symptom(s) listed on models with serial numbers that begin with 22.

Subject: Video tape removal

Ref.# 02A-9602

Symptom: The VCR will not eject the video tape.

Part(s) required: Location Part Number Description

H535	70790539	Lever - Door Opener
------	----------	---------------------

Corrective Action: Replace the door opener lever (H535) located on the left side of the cassette loading mechanism. Refer to the figure below for the location and position of the lever.

