




CORRECTION OF SERVICE MANUAL

Date: Aug 5, 1999

No.: SI-H54009

MODEL No.	S/M No.	PG	MODEL No.	S/M No.	PG
DV-525/KU	RRV2158	11	DV-525/KC	RRV2158	11
DV-525/WV	RRV2158	11	DV-525/WY	RRV2158	11
DV-525/WY/SP	RRV2158	11	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____

The following part will **not** be available as spare parts.

Mark	No.	Description	Part No.
	5	Pickup Assy	VWY1055
* NSP			

PIONEER ELECTRONIC CORPORATION

,MANAGER

Service Engineering Section
Service Division

Memo: RA, 65

