



NOTES:

1. TERMINAL STRIP MUST HAVE ALL LEADS "HOOKED" IN LUG BEFORE SOLDERING
2. NOTE FUSE IS 1-1/2 AMP SLO BLOW
3. NOTE MOV IS 220V. (105015)

T100S FOREIGN WIRING - A.C.

SCALE: ✓

APPROVED BY:

DRAWN BY DJT

DATE: 9-4-89

REVISED 4-11-90

ADA:

DRAWING NUMBER REV

B663 A



<http://www.adadepot.com>