

SONY

Hi-Fi Products Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-C40/50

No. 107


Subject: Reference Number Correction -
Front/Rear Feet

Date: February 2, 1990

Symptom:
(**)

Reference Numbers 35 and 39 are reversed in the exploded view on page 19.

Solution: Please make the corrections in the service manual as shown below.



Compact Disc

CSA-13

Reference: KCP

PRINTED IN U.S.A.
CSA-13190-8