

Model: KP-53HS10, KP-61HS10**No. 510****Subject:** Circuit change for white saturation**Date:** November 27, 2000**Symptom:**
(1322)Saturation/low resolution is seen on the screen with high level white signal.
Saturation starts around 1.2vp-p of signal level on all Y, Pb, Pr inputs.**Solution:** If the customer should complain of the symptom above the following resistor values must be changed, on the conductor side of the "A" Board.

Ref	A Board Location	Former	New	Part Number
R1462	D-9	0 Ohm	390 Ohm Chip res.	1-216-641-11
R1467	F-8	0 Ohm	390 Ohm Chip res.	1-216-641-11
R1471	F-8	0 Ohm	390 Ohm Chip res.	1-216-641-11

Continue next page

