

Model: KV-13FM12, KV-13FM14, KV-20FS12
KV-20FV12, KV-24FV12, KV-27FS12
KV-27FS16, KV-27FV16, KV-32FS12
KV-32FS16**No. 516R1****Subject:** Intermittent Picture When Playing Back DVD
on the BA-5 Chassis.**Date:** March 22, 2001**Symptom:**
(2312)

When playing back a DVD the picture will intermittently blank out and the video label will appear.

Solution: If the customer should complain of this symptom please make the following changes to the MA, or MB Board.**Models:** KV-13FM12, KV-13FM13, KV-20FS12, KV-20FV12, KV24FV12

Ref	Location	Description Former	Description New	Part Number
R1020	Base Q1009 MB BOARD C-4	100K 1/10w	150K 1/10w	1-216-101-11

Models: KV-27FV16, KV-32FS12, KV-32FS16

Ref	Location	Description Former	Description New	Part Number
R077	Base Q006 MA BOARD D-3	100K 1/10w	150K 1/10w	1-216-101-11

Models: KV-27FS12, KV-27FS16

Ref	Location	Description Former	Description New	Part Number
R077	Base Q006 MA BOARD C-1	100K 1/10w	150K 1/10w	1-216-101-11

