

Model: KV-32S42, KV-32S66, KV-32V42
KV-35S42, KV-35S66, KV-35V42

No. 530

Subject: Schematic diagram incorrect, audio section

Date: May 15, 2001

Symptom:
(818X)

The schematic diagram of the audio circuit is incorrect.

Solution: Please correct your service manual with the information below.

