

<b>VESTEL</b> ELEKTRONİK A.Ş.	<b>TECHNICAL CHANGE BULLETIN</b> <b>TEKNİK DEĞİŞİKLİK BÜLTENİ</b>	CHANGE NO: 92
		REF NO :
		DATE :15.10.2001

AFFECTED MODELS: CHASSIS 11AK30 ALL MODELS

START DATE : 15.10.2001

REASONS OF CHANGE: PROBLEM TO CONTROL TV WITH REMOTE CONTROLLER.

REMOTE CONTROLLER DOESN'T OPERATE. IR-SIGNAL IS VISIBLE ON OSSCILOSCOP SCREEN, BUT REMOTE CONTROLLER STILL DOESN'T OPERATE.

**OUT**

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK30	30012581	CAP SMD 1NF 50V K R (0603)	C509	1
2					
3					
4					
5					

**IN**

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1					
2					
3					
4					
5					

APPLICATION ENGINEER	APPLICATION ENGINEER CHIEF	APPLICATION ENGINEER MANAGER
B.ISCAN		BEYHAN DAĞITAN