

| | | |
|----------------------------------|--|------------------|
| VESTEL ELEKTRONİK A.Ş. | TECHNICAL CHANGE BULLETIN TEKNİK DEĞİŞİKLİK BÜLTENİ | CHANGE NO: 104 |
| | | REF NO : |
| | | DATE :19.12.2001 |

AFFECTED MODELS: ALL 11AK19-Y11 CHASSIS BASED TV MODELS.

START DATE : 20.12.2001

REASONS OF CHANGE:

DEFECT OF THE RGB AMPLIFIER TDA 6108 (IC 901)

TO CATCH A BETTER RELIABILITY ACCORDING SPARKS OF THE PICTURE TUBE THE LAYOUT OF THE CRT-BOARD WAS CHANGED .

NOTE 1: THE SPARE-PART NUMBER OF THE COMPLETE INSERTED CRT-BOARD DOES NOT CHANGED

OUT

| NO | PCB CODE | VESTEL CODE | COMPONENT NAME | POSITION NUMBER | QUANTITY |
|----|-----------|-------------|---------------------|-----------------|----------|
| 1 | 11TP19-Y2 | 30016007 | PCB 11TP19Y2 | - | 1 |
| 2 | 11TP19-Y2 | 30001242 | RES FUSE 1/4W 47R J | R914 | 1 |
| 3 | | | | | |
| 4 | | | | | |
| 5 | | | | | |

IN

| NO | PCB CODE | VESTEL CODE | COMPONENT NAME | POSITION NUMBER | QUANTITY |
|----|-----------|-------------|----------------|-----------------|----------|
| 1 | 11TP19-Y3 | 30016572 | PCB 11TP19Y3 | - | 1 |
| 2 | 11TP19-Y3 | 30002583 | JUMPER WIRE | R914 | 1 |
| 3 | | | | | |
| 4 | | | | | |
| 5 | | | | | |

| | | |
|-------------------------|----------------------------------|---------------------------------|
| APPLICATION ENGINEER | APPLICATION ENGINEER CHIEF | APPLICATION ENGINEER MANAGER |
| F. UZGAN | | BEYHAN DAĞITAN |