

VESTEL ELEKTRONİK A.Ş.	TECHNICAL CHANGE BULLETIN TEKNİK DEĞİŞİKLİK BÜLTENİ	CHANGE NO:
		REF NO : 108
		DATE :28.02.2002

AFFECTED MODELS: AK19 HITACHI CP2842AN , CL2842AN , C2842N

START DATE : 28.02.2001

REASONS OF CHANGE:
TO IMPROVE DIODE D825 OPERATING CONDITION

OUT

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	AK19	30001318	DIODE BA159 1A/800V	D825	1
2					
3					
4					
5					

IN

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	AK19	30007681	UF5407 3A/800V	D825	1
2					
3					
4					
5					

CUSTOMER SUPPORT ENGINEER	QUALITY MANAGER
S.DEMIRKAYA	ALI TUNC CAN