

VESTEL ELEKTRONİK A.Ş.		CHANGE BULLETIN (TCN)		CHANGE NO: 44 REF NO :ÜDM- 148	
AFFECTED MODELS: ALL MODELS WITH 11AK19 CHASSIS.					
START DATE : 01.03.1999					
REASONS OF CHANGE: TO IMPROVE SYNCRONISATION PERFORMANCE .					
NOTE : This resistor must be connected between the collector and the base pins of transistor Q410 under the PCB.					
OUT					
NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK19-5/8	-	-	-	-

IN					
NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK19-5/8	30000665	RES CF 1/4W 33K J	RX012 (NOTE)	1

PRODUCTION SUPPORT ENGINEER	PRODUCTION SUPPORT CHIEF	PRODUCTION SUPPORT MANAGER
YILDIRAY BAŞKURT		CELAL ÖZKUL