

VESTEL ELEKTRONİK A.Ş.	CHANGE BULLETIN (TCN)	CHANGE NO: 76 REF NO : UMB-0251
-----------------------------------	----------------------------------	--

AFFECTED MODELS: ALL STEREO MODELS INCLUDING 11AK19 CHASSIS WITH TDA9875A SOUND BOARD.

START DATE : 12.04.2000

REASONS OF CHANGE: TO OVERCOME OSILATION PROBLEM ON TEAC 8411 MODELS.

OUT

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
-	-	-	-	-	-

IN

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK19	30000609	RES SMD 1/10W 2.2R J	R324, R309	2

APPLICATION ENGINEER	APPLICATION ENGINEERING CHIEF	APPLICATION ENGINEERING MANAGER
-	YILDIRAY BAŞKURT	BEYHAN DAĞITAN