

<b>VESTEL ELEKTRONİK A.Ş.</b>	<b>CHANGE BULLETIN (TCN)</b>	<b>CHANGE NO: 80 REF NO : -</b>
-----------------------------------	----------------------------------	-------------------------------------

**AFFECTED MODELS: ALL MODELS WITH 11AK19-B1 AND 11AK19-E3 CHASSIS.**

**START DATE : 1<sup>th</sup> July.2000**

**REASONS OF CHANGE: All models with 11AK19-B1 & 11AK19-E3 chassis including SDA54XX controller family have been replaced with 11AK19-P chassis including SDA55XX controller family.**

**NOTE 1: The ordering code of the new service manual for 11AK19-P chassis is 50014848.**

**NOTE 2: New controller SDA55XX is not compatible with the previous ones SDA52XX & SDA54XX from the view of hardware side. For detailed explanation please refer to Service Manual /11AK19-P.**

OUT

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK19-B1	Model Based	11AK19-B1 CHASSIS	-	1
2	11AK19-E3	Model Based	11AK19-E3 CHASSIS	-	1

IN

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK19-P	Model Based	11AK19-P	-	1

APPLICATION ENGINEER	APPLICATION ENGINEERING CHIEF	APPLICATION ENGINEERING MANAGER
-	YILDIRAY BAŞKURT	BEYHAN DAĞITAN