



SERVICE MANUAL

REAR PROJECTION TELEVISION

AV-48WP74/HA, AV-56WP74/HA

BASIC CHASSIS

SB3

Supplementary

Please be informed that there are errors in the following service manual.
AV-48WP74/HA, AV-56WP74/HA (No.52105 2003/4)

CORRECTION ITEM

PRINTED WIRING BOARD PARTS LIST (Page 3-18)

DIGITAL CONVERGENCE MODULE PW BOARD ASS'Y
(SSB0K070A-M2) [AV-48WP74]
(SSB0K069A-M2) [AV-56WP74]

△ Ref.No.	Part No.	Part Name	Description	Local
SSB0K070A-M2	SSB0K069A-M2	DIGITAL CONVERGENCE MODULE PWB	DIGITAL CONVERGENCE MODULE PWB	AV-48WP74
SSB0K069A-M2	SSB0K070A-M2	DIGITAL CONVERGENCE MODULE PWB	DIGITAL CONVERGENCE MODULE PWB	AV-56WP74

MI-COM & DIST MODULE PW BOARD ASS'Y
(SSB0D070A-M2) [AV-48WP74]
(SSB0D069A-M2) [AV-56WP74]

△ Ref.No.	Part No.	Part Name	Description	Local
SSB0D070A-M2	SSB0D069A-M2	MI-COM & DIST MODULE PWB	MI-COM & DIST MODULE PWB	AV-48WP74
SSB0D069A-M2	SSB0D070A-M2	MI-COM & DIST MODULE PWB	MI-COM & DIST MODULE PWB	AV-56WP74

SECTION 1 PRECAUTION

Please refer to "AV-48WP74/HA and AV-56WP74/HA (No.52105)" about this section.

SECTION 2 SPECIFIC SERVICE INSTRUCTIONS

Please refer to "AV-48WP74/HA and AV-56WP74/HA (No.52105)" about this section.

SECTION 3 DISASSEMBLY

Please refer to "AV-48WP74/HA and AV-56WP74/HA (No.52105)" about this section.

SECTION 4 ADJUSTMENT

Please refer to "AV-48WP74/HA and AV-56WP74/HA (No.52105)" about this section.

SECTION 5 TROUBLESHOOTING

Please refer to "AV-48WP74/HA and AV-56WP74/HA (No.52105)" about this section.



Victor Company of Japan, Limited
Display Category 12, 3-chome, Moriya-cho, Kanagawa-ku, Yokohama-city, Kanagawa-prefecture, 221-8528, Japan

