

SONY

TV Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: KV-27XBR25/27XBR35/27XBR95S/32XBR25/
32XBR35/32XBR90S/32XBR95S

No.160R1

Subject: FN Chassis Board Replacement Policy

Date: March 31, 1993

This bulletin supersedes TV Products Service Bulletin No.160.

Symptom:
(**)

Replacement Board Policy

Solution:

The following boards may be repaired or exchanged:

| MODEL | DESCRIPTION | PART NUMBER |
|-------------|-------------|--------------|
| KV-27XBR25 | E1 Board | A-1346-057-A |
| KV-27XBR25 | E2 Board | A-1342-547-A |
| KV-27XBR25 | M Board | A-1306-415-A |
| KV-27XBR25 | P1 Board | A-1195-051-A |
| KV-27XBR25 | X2 Board | A-1394-363-A |
| KV-27XBR25 | Y2 Board | A-1394-362-A |
| KV-27XBR35 | E1 Board | A-1346-057-A |
| KV-27XBR35 | E2 Board | A-1342-547-A |
| KV-27XBR35 | M Board | A-1306-415-A |
| KV-27XBR35 | P1 Board | A-1195-051-A |
| KV-27XBR35 | X2 Board | A-1394-363-A |
| KV-27XBR35 | Y2 Board | A-1394-362-A |
| KV-27XBR95S | E1 Board | A-1346-059-A |
| KV-27XBR95S | E2 Board | A-1346-060-A |
| KV-27XBR95S | M Board | A-1306-417-A |
| KV-27XBR95S | P2 Board | A-1195-053-A |
| KV-27XBR95S | P4 Board | A-1195-054-A |
| KV-27XBR95S | X3 Board | A-1394-367-A |

CSV-1 Color TV

(Continued)

Reference:



PRINTED IN U.S.A.
CSA-1393-9

| MODEL | DESCRIPTION | PART NUMBER |
|-------------|-------------|--------------|
| KV-27XBR95S | Y2 Board | A-1394-366-A |
| KV-32XBR25 | E1 Board | A-1346-051-A |
| KV-32XBR25 | E2 Board | A-1346-052-A |
| KV-32XBR25 | M Board | A-1306-415-A |
| KV-32XBR25 | P1 Board | A-1195-051-A |
| KV-32XBR25 | X2 Board | A-1394-363-A |
| KV-32XBR25 | Y2 Board | A-1394-362-A |
| KV-32XBR35 | E1 Board | A-1346-051-A |
| KV-32XBR35 | E2 Board | A-1346-052-A |
| KV-32XBR35 | M Board | A-1306-415-A |
| KV-32XBR35 | P1 Board | A-1195-051-A |
| KV-32XBR35 | X2 Board | A-1394-363-A |
| KV-32XBR35 | Y2 Board | A-1394-362-A |
| KV-32XBR90S | E1 Board | A-1346-059-A |
| KV-32XBR90S | E2 Board | A-1346-060-A |
| KV-32XBR90S | M Board | A-1306-417-A |
| KV-32XBR90S | P4 Board | A-1195-054-A |
| KV-32XBR90S | Y2 Board | A-1394-366-A |
| KV-32XBR95S | E1 Board | A-1346-059-A |
| KV-32XBR95S | E2 Board | A-1346-060-A |
| KV-32XBR95S | M Board | A-1306-417-A |
| KV-32XBR95S | P2 Board | A-1195-053-A |
| KV-32XBR95S | P4 Board | A-1195-054-A |
| KV-32XBR95S | X3 Board | A-1394-367-A |
| KV-32XBR95S | Y2 Board | A-1394-366-A |

If it is exchanged, please return the original board together with a copy of the NARDA form to the following address below:

Sony Service Company
 Technical Dept./TV Group
 Mail Drop T1-3
 123 Tice Blvd.
 Woodcliff Lake, N. J. 07656

For board replacement authorization, please contact your Technical Supervisor.