

KV-27XBR35/32XBR35

RM-Y113/TDR-IF310

SONY[®] SERVICE MANUAL

US Model

KV-27XBR35

Chassis No SCC-F16D-A

KV-32XBR35

Chassis No SCC-F16A-A

Canadian Model

KV-27XBR35

Chassis No. SCC-F17C-A

KV-32XBR35


Chassis No SCC-F17A-A

CORRECTION-1

Correct the service manual as shown below
File this Correction with the Service Manual.

 indicates corrected portion (page 165)

SECTION 8 ELECTRICAL PARTS LIST

INCORRECT	CORRECT
A-4503-953-A HEADPHONE TDR-IF310	Delete 



g-964-849-91

Sony Corporation
TV Group

English
93CE0948-1
Printed in Japan
019933