

KV-27XBR35 / 32XBR35

RM-Y113/TDR-IF310

SONY SERVICE MANUAL


US Model

KV-27XBR35
Chassis No. SCC-F16D-A
KV-32XBR35
Chassis No. SCC-F16A-A

CORRECTION-2 Canadian Model


Correct the service manual as shown below.
File this collection with the service manual.

KV-27XBR35
Chassis No. SCC-F17C-A
K V-32XBR35
Chassis No. SCC-F17A-A

 : Corrected portion

SECTION 5 EXPLODED VIEWS

8. PICTURE TUBE (See page 165)

Incorrect				Correct			
REF. NO.	PART. NO.	DESCRIPTION		REF. NO.	PART. NO.	DESCRIPTION	
	A-4503-953-A	HEADPHONE	TDR-IF310		A-4503-958-A	HEADPHONE	TDR-IF310
							



9-964-849-92

Sony Corporation
TV Group

English
93EJ0948-1
Printed in Japan
© 1993. 5