

Model: KP-48S65, KP-48S65R**No. 358****Subject:** No Service Manual for the KP-48S65R**Date:** May 18, 1998**Symptom:**
(1XXX)

The KP-48S65R is being sold to rental stores. This unit is the same electrically as the KP-48S65. The only difference is the contrast screen comes with this unit whereas the KP-48S65 has it as an option. There will be no Service Manual issued on the KP-48S65R .

Solution:

Below are the part numbers of the screen and brackets that are different then those listed in the Service Manual for the KP-48S65.

Description	Part Number
Screen Holder (S)	4-058-892-01
Screen Holder (L)	4-058-893-01
Screen Holder Cushion	N/A
Contrast Screen (SCN-48SX2)	4-064-651-01
Adjustment Description Sub-contrast	Adjustment level 1.75v (pedestal to peak)

NOTE:

If for some reason the contrast screen was removed from this model, the remaining two screens would have a "loose" fit. To correct this situation, the contrast screen must be replaced, or the Screen Holder (S) and (L) replaced with the Screens Holders used in the KP-48S65.

If the "A" Board is replaced the adjustment for sub-contrast will need to be readjusted to 1.75v. This is due to the addition of the contrast screen. The contrast level will need to be adjusted due to the contrast screen.