

5. Electrical Part List

5-1 HLP5063WX/XAP Service Item

You can search for the updated part code through ITSELF web site.

URL: <http://itself.sec.samsung.co.kr>

Loc.No.	Code No.	Description;Specification	Q'ty	SA/SNA
D0254	AA32-00012A	MODULE REMOCON;ORC-50HF2,38KHZ,940NM,MES	1	S.A
M0125	BP39-00106C	CBF SIGNAL-DVI(D);HLP5063WX,24P/24P,2027	1	S.A
M0018	BP97-00825D	ASSY MICOM;L62B,29DL32,T-ATLNUS-1040,05	1	S.A
M0045	BP64-00380A	CABINET BACK-TOP;50L3,HIPS,3.5,HB,GRAY	1	S.A
T0003	BP96-00532C	ASSY COVER P-FRONT;50L3,HIPS,HB,GR503,BK	1	S.A
T0015	BP64-00379B	CABINET BACK-BOT;50L3,HIPS,T3.5,V0,Gray,	1	S.A
T0049	BP47-00021A	LAMP-BALLAST;EUC 120 P/H11,120W,130mm ca	1	S.A
T0053	BP67-00109A	SCREEN FRESNEL;50W,1126*646,2T	1	S.A
T0054	BP67-00153A	SCREEN LENTI;50W,MS,1126*646,2.1T	1	S.A
T0074	BP59-00048C	REMOCON;ATLANTIS,TM76A,47,SMV-5012,EX	1	S.A
T0091	BP94-02140C	ASSY PCB MISC-SIDE AV;HLP5063W,L62B,ATLA	1	S.A
T0120	BP94-02141H	ASSY PCB POWER;HLP46/50/56/61(L3),L62B,1	1	S.A
T0129	BP96-00822L	ASSY ENGINE P-DLP PWL3;50L3(AIR),PHILIPS	1	S.A
T0131	BP96-00568E	ASSY COVER P-BACK BOT;L3 ALL,HIPS,V0,GRY	1	S.A
T0132	BP94-02065A	ASSY PCB MISC-DIGITAL;HLP5063,L62B,BP94-	1	S.A
T0145	BP94-02140N	ASSY PCB MISC-ANALOG;L62B,EXPORT	1	S.A
T0175	BP96-00543A	ASSY SPEAKER P;8ohm,BP96-00542A,3001-001	1	S.A
T0260	BP67-00096A	MIRROR;MIRROR FRONT 50",GLASS,1100X580X5	1	S.A
T0269	BP94-00485A	ASSY PCB S-ACTUATOR/SUB DETECT;HLP5063WX	1	S.A
T0703	BP96-00678D	ASSY DMD BOARD P;L3 Philips,DMD BOARD,DM	1	S.A
T0751	BP96-00690A	ASSY BALLAST P;L3,SERVICE BALLST	1	S.A
T0753	BP94-02149K	ASSY PCB S-ACTUATOR;DP,BP41-00121A,L62B,	1	S.A
T0888	BP96-00826A	ASSY LAMP P;L3,LAMP SERVICE,PHILIPS 120W	1	S.A
T0889	BP96-00674A	ASSY COLOR WHEEL P;SVP-50L3HR	1	S.A
T0952	BP59-00055A	MODULE-RF SPLITTER;RF SWITCH,UMX-NT-034,	1	S.A

MEMO