

TOSHIBA AMERICA CONSUMER PRODUCTS, INC

TOSHIBA

VCR / CAMERA SERVICE BULLETIN NO: 62

DATE: MAY / JUNE

MODELS: SEE LIST BELOW


SUBJECT: ACE Head Assembly Part Substitution

Symptom: Part Number Change

Corrective
Action:


ACE Head Assemblies 70182056 and 70184010 are no longer available. Substitute with ACE Head Assembly 70182078. After replacing ACE Head Assembly with substitute 70182078 readjust the bias current to 3.1 mV.

OLD ACE HEAD ASSEMBLY
(70182056 or 70184010)



Core : Black

NEW ACE HEAD ASSEMBLY
(70182078)



Core : Silver

MODELS USING ACE HEAD 70182056					
M2100	M2130	M2320	M3440	M5130	M5330
M2104	M2134	M2330	M5100	M5300	M5500
M2120	M2200	M2700	M5120	M5320	M5530
M2124	M2220	M3430			
MODELS USING ACE HEAD 70184010					
DX3	M6005	M6255	M6455	M7602	M7735
DX400	M6200	M6270	M6550	M7605	M7850
M6000	M6230	M6275	M6555	M7730	M7855
M6002	M6235	M6450	M7600		