

# TOSHIBA AMERICA CONSUMER PRODUCTS, INC

# TOSHIBA

## VCR / CAMERA SERVICE BULLETIN NO: 65

DATE: MAY / JUNE

MODELS: M-221, M-222, M-226

SUBJECT: Part Substitution

Symptom: No Power

Corrective  
Action:

Replace the diodes type 1N5392 (TAPG) with type 1N4002 (TAGP).  
(See chart below for locations per model.)

### M-221/226 Series

Location	Part No.	Vendor	Description
D107	70693202 BZ43002B BZ430021	K	Diode, 1N4002 (TAGP)
D108			

### M-222 Series

Location	Part No.	Vendor	Description
D1103	70693202 BZ43002B BZ430021	K	Diode, 1N4002 (TAGP)
D1104			