

# TOSHIBA AMERICA CONSUMER PRODUCTS, INC.

# TOSHIBA

## VCR / CAMERA SERVICE BULLETIN NO:66

DATE: July / August

MODELS: M222

SUBJECT: Part Change

**Symptom:** The capstan motor will not turn.

**Corrective**

**Action:** When replacing diode type 1N4001 use replacement diode specified in the chart below.

Location	Part No.	Vendor	Reference No.	Description
D105 D106 D107 D108 D109 D110	BZ430028 BZ430021 70693202	K	B4104-0046	Diode 1N4002GP
D112 D113	BZ430029	K	B4104-0047	Diode GP15D