

# TOSHIBA AMERICA CONSUMER PRODUCTS, INC

# TOSHIBA

## VCR / CAMERA SERVICE BULLETIN NO: 68A

DATE: November / December 1992

MODELS: M-458, M-468, M-657, M-658,  
M-668, M-758


SUBJECT: S-Soft Brake Lever (Corrected Part Number from # 68)

**Symptom:** Will not play due to loading malfunction.


**Corrective Action:** Replace the soft brake lever K128 with the new black colored one.

**Required Part:**

Location	Part No.	Vendor	Description
K128	70363026	J	Lever, S-Soft Brake



**White  
(Previous)**



**Black  
(Current)**