

TOSHIBA AMERICA CONSUMER PRODUCTS, INC.

TOSHIBA

VCR / CAMERA SERVICE BULLETIN NO:69

DATE: NOV 1993

MODELS: M222

SUBJECT: Part Change

***** THIS BULLETIN SUPERSEDES VCR 65 AND VCR 66 *****

- Symptom: 1. No Power (Dead)
2. The Cylinder motor does not turn
3. The Capstan motor does not turn.

Corrective

Action: Check diodes D105, D106, D108, D109, D110, D112, D113, D1103 and D1104. If any of the diodes have failed replace ALL the diodes listed above with the new part numbers listed in the chart below.

Location	Reference Number	New Part Number	Description
D105 D106 D108 D109 D110 D1103 D1104	B4104-0046	BZ430028	Diode 1N4002GP
D112 D113	B4104-0047	BZ430029	Diode GP15D