

TOSHIBA AMERICA CONSUMER PRODUCTS, INC.

TOSHIBA

VCR / CAMERA SERVICE BULLETIN NO:70

DATE: NOV 1993

MODELS: M449

SUBJECT: Part Change

Symptom: Part Change

Corrective

Action: When replacing the microprocessor HD6433724 A82F (Part # 70795654) use the HD6433427 B12F (Part # 70796055). The new IC HD6433724 B12F can be substituted for the HD6433724 A82F without any modifications.

Location	Part No.	Reference No.	Description
IC601	70796055	B4002-0284	IC-MCU HD6433724 B12F