

TOSHIBA AMERICA CONSUMER PRODUCTS, INC.

TOSHIBA

**VCR / CAMERA / LD
SERVICE BULLETIN
NO:76**

DATE: SEPT1994

**MODELS: M2390, M239C, M43,
M4390, M439C**

SUBJECT: Parts Substitution

Symptom: Parts Substitution

Corrective

**Action: Use the new diode, Part Number BZ480025, when replacing
the diodes listed below due to increased parts reliability.**

Location	Part No.	Description
D201 D202 D203 D204 D205 D401 D701 D702 D704 D705 D708 D709 D711	BZ480025	Diode, 1SS254T