

1996**TOSHIBA AMERICA CONSUMER PRODUCTS, INC.***Date: MAR 96***TECHNICAL BULLETIN****No. VCR9603****Product: VCR****Countries affected: USA, CANADA**

MODEL	VCR					TV/VCR
USA	M-650	M-660	M-750	M-760	M-770	CV27D48
CANADA	M-650C	M-660C	M-750C	M-760C		
JAPAN			M-750J			

NOTE: The information provided below should only be used if you encounter the symptom(s) listed.

Subject: Cassette loading/eject.

Ref.# 10A-9503

Symptom: A cassette loading/eject malfunction may occur due to possible wear of the T-Loading assembly gear.

Replacement Kit:

Location	Part No.	Description
----------	----------	-------------

-	70903974	Slider Assy Kit, Loading
---	----------	--------------------------

Parts kit #70903974 contains the following:

Location	Part No.	Description
----------	----------	-------------

B490	70322518	Slider Assy, Loading
B470	70322516	Loading Assy, T
B500	70396193	Washer, 2.6 x 6 x 0.5

Corrective Action:

- 1) Replace the Slider Assy, Loading (B490).
- 2) Replace the Loading Assy, T (B470).
- 3) Replace the Washer (B500).

Refer to the service manual for replacement procedures.