

ADA SIGNAL PROCESSORS, INC.

DATE: 9/15/87

PARTS QUALIFICATION - ENGINEERING REPORT

TESTED BY: [Signature]

PART QUALIFIED FOR ADA PART NO. _____

ADA DRAWING NO. _____

PART DESCRIPTION

Domestic xformer for MP-1

PURCHASE ORDER NO. _____

VENDOR

Delnetics

VENDOR PN

Delnetics 582

NEW PART



ALTERNATE SOURCE



COST REDUCTION ALT.



USE FOR ASSEMBLY

240067

RECOMMENDATION

increase output of +/-15V
secondary so it can run
lower without hum

TEST	P	F	N/A	COMMENT
THERMAL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
SOLVENT	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
MECHANICAL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<u>Barely</u>
IN CIRCUIT	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>+15V dereregulates @ 96VAC - Not to spec.</u>
COSMETIC	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>No bottom plate - Potting not set when rec'd</u>
LEAKAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

COMMENTS:

Digit omitted from part number
is 24067 - S/B 240067

101286CG

Approved by: _____