

VESTEL ELEKTRONİK A.Ş.	TECHNICAL CHANGE BULLETIN TEKNİK DEĞİŞİKLİK BÜLTENİ	CHANGE NO: 90
		REF NO : UMB_873
		DATE :15.10.2001

AFFECTED MODELS: CHASSIS 11AK30 MODELS WITH MASK TYPE MICRO CONTROLLER.

NOTE : ON OTP IC IS WRITTEN : ST92T195D7B1

ON MASK IC IS WRITTEN SW-VERSION OF IC : A005, B022, D021, E019 etc...

START DATE : 15.10.2001

REASONS OF CHANGE: RESET PROBLEM

TV SWITCH ON IN 20-30 SECONDS, AFTER PRESSING REMOTE CONTROLLER BUTTONS OR FRONT PANEL BUTONS SUCCESSIVELY.

OUT

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK30	30001369	DIODE ZENER 3.6V ZPD	D513	1
2	11AK30	30012579	CAP SMD 82PF 50V J (0603)	C521,C522	2
3	11AK30	30000345	CAP EL 10UF 50V M	C502	1
4					
5					

IN

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK30	30001339	DIODE ZENER 3.9V	D513	1
2	11AK30	30012562	CAP SMD 15PF 50V J (0603)	C521,C522	2
3	11AK30	30000396	CAP EL 47UF 16V M	C502	1
4					
5					

APPLICATION ENGINEER	APPLICATION ENGINEER CHIEF	APPLICATION ENGINEER MANAGER
B.ISCAN		BEYHAN DAĞITAN