

<b>VESTEL</b> <b>ELEKTRONİK A.Ş.</b>	<b>TECHNICAL CHANGE BULLETIN</b>	CHANGE NO: 119
		REF NO :
		DATE :23.07.2001

AFFECTED MODELS: ALL MODELS 11AK19 WITH PFC

START DATE : 23.07.2001

REASONS OF CHANGE:

To reduce heat load of the diode

OUT

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	AK19	30007681	DIODE UF5407	D822	1
2					

IN

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	AK19	20061184	MD.ASY.DYD19P-11DYP19P BOARD	D822	1
2					
3					
4					
5					

CUSTOMER SUPPORT ENGINEER	QUALITY MANAGER
ERCAN ÖZ	ALI TUNC CAN