

VESTEL ELEKTRONİK A.Ş.	CHANGE BULLETIN (TCN)	CHANGE NO: 027 REF NO :ÜDM-468
-----------------------------------	----------------------------------	---

AFFECTED MODELS: AMERICAN MODELS WITH PAL M,N – NTSC M, 110°, MONO

START DATE :03/09 /1998

REASONS OF CHANGE: TO INCREASE THE AUDIO OUTPUT POWER LEVEL.

OUT

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK19	3311831030	RES. SMD 18K J	R106	1
2					
3					
4					
5					

IN

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK19	3311031030	RES. SMD 10K J	R106	1
2					
3					
4					
5					

PRODUCTION SUPPORT ENGINEER	PRODUCTION SUPPORT CHIEF	PRODUCTION SUPPORT MANAGER CELAL ÖZKUL