

VESTEL ELEKTRONİK A.Ş.	CHANGE BULLETIN (TCN)	CHANGE NO: 43 REF NO :ÜDM- 010, 011
-----------------------------------	----------------------------------	--

**AFFECTED MODELS: ALL TV MODELS WITH 11AK19 CHASSIS INCLUDING MSP34XX SOUND
PROCESSOR BASED ST. SOUND BOARD.**

START DATE : 15.01.1999

REASONS OF CHANGE: TO IMPROVE SOUND PERFORMANCE.

**NOTE 1: MUST BE CONNECTED BETWEEN THE PIN OF S402 WHICH IS CONNECTED TO THE PIN 7 OF
PL300 AND THE GROUND PIN OF C333.**

NOTE 2: MUST BE CONNECTED BETWEEN THE PIN14 OF PL301 AND THE GROUND POINT OF J110.

**NOTE 3 :MUST BE CONNECTED BETWEEN THE GROUND POINT OF C401 AND THE GROUND POINT OF
C293. CONNECTION BETWEEN THE PIN 27 OF IC301 AND HP-GROUND MUST BE REMOVED.**

OUT

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11ST19-A3	3821080500	SMD JUMPER	S401, S402	2
2	11ST19-A3	5913225000	JUMPER WIRE	J111	1
3	11ST19-A3	3061020241	CAP SMD 1 NF 50V	C101, C107	2
4	11ST19-A3 (With HP)	3081010356	CAP EL 100uF /16V	C293	1

IN

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11ST19-A3	4942010001	CABLE 0.6 MM BLUE	NOTE1 (6 CM)	1
2	11ST19-A3	4942010001	CABLE 0.6 MM BLUE	NOTE 2 (3 CM)	1
3	11ST19-A3	3065620241	CAP SMD 5.6NF/50V	C101, C107	2
4	11ST19-A3 (With HP)	3083310356	CAP EL 330uF /16V	C293	1
5	11ST19-A3 (With HP)	4942010001	CABLE 0.6 MM BLUE	NOTE 3 (6 CM)	1

PRODUCTION SUPPORT ENGINEER	PRODUCTION SUPPORT CHIEF	PRODUCTION SUPPORT MANAGER
YILDIRAY BAŞKURT		CELAL ÖZKUL