

VESTEL ELEKTRONİK A.Ş.	CHANGE BULLETIN (TCN)	CHANGE NO: 63 REF NO : UMB-401
-----------------------------------	----------------------------------	---

AFFECTED MODELS: ALL 11AK19 MODELS.

START DATE : 15/07/1999

REASONS OF CHANGE: NEW PCB VERSION.

OUT

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK19	30007878	11AK19-8A PCB	-	1
2					
3					
4					
5					

IN

NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11AK19	30002409	11AK19-B PCB	-	1
2					
3					
4					
5					

PRODUCTION SUPPORT ENGINEER	PRODUCTION SUPPORT CHIEF	PRODUCTION SUPPORT MANAGER
YILDIRAY BAŞKURT		CELAL ÖZKUL