


PROCESS SCHEMATIC DIAGRAM

R,G,B SIGNAL
DIGITAL R,G,B SIGNAL


DIGITAL Y SIGNAL
DIGITAL C SIGNAL



NOTE:DO NOT USE ANY PART NUMBER SHOWN ON THIS SCHEMATIC DIAGRAM FOR ORDERING. WHEN YOU ORDER A PART,PLEASE REFER TO PARTS LIST.

NOTE:THE MEASUREMENT MODE OF THE DC VOLTAGE ON THIS DIAGRAM IS STOP MODE WITH AIM THE CAMERA AT THE LOGARITHMIC GRAY SCALE CHART.

PROCESS SCHEMATIC DIAGRAM



PROCESS SCHEMATIC DIAGRAM