

**SONY**

TV Products

## Service Bulletin

CSV-1

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** KPR-41EXR95/46EXR15/53EXR15      **No. 196**  
KV-27XBR25/27XBR35  
KV-32XBR25/32XBR35

**Subject:** Change in IC for picture in picture circuit      **Date:** February 18, 1994

**Symptom:**  
(\*\*)

The IC below, on the P1 board P/N A-1195-051-A, will be discontinued. Once KCP stock runs out please use the new IC listed below.

**Solution:**

REF	FORMER		NEW	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
IC-3007	SDA9086-3	8-759-046-27	SDA9086-5	8-759-248-91

Reference: FPR-O  
AUTOFLAGGED - NO



PRINTED IN USA  
CSV-1294-5