

4. Service Item

4-1 SPP4231KX/XAA

You can search for the updated part code through ITSELF web site.

URL: <http://itself.sec.samsung.co.kr>

LOC.NO.	CODE NO.	SPEC	Q'TY
D0254	AA32-00013B	MODULE REMOCON;346HF5,38KHz,940mm,MESH,H	1
T0568	AA39-30007A	CBF IF;- ,T,100mm,1365#26	1
TU1401	BN40-00050A	TUNER;TMQH6-003B,PDP-NELSON,NTSC,181CH,4	1
T0074	BN59-00376B	REMOCON;TM-75,MUSE_UO,S3C1860XNOSMB1,36,	1
T0079	BN94-00521C	ASSY PCB MISC-MAIN; ,SP-P4231,D65C,BN41-0	1
T0098	BN94-00607A	ASSY PCB MISC-CONTROL;PS42D4/42V4,D65C,N	1
T0452	BN95-00368A	ASSY SUB PCB-SOUND;PS42P4A,D68A,NAPOLEON	1
T0001	BN96-00314E	ASSY COVER P-BACK;42D4,ASSY C/BACK	1
T0175	BN96-00614F	ASSY SPEAKER P;8ohm,PSN4231,One packing,	1
M0003	BN96-01207A	ASSY COVER P-FRONT;42D4,SEA,HIPS V0,BLK	1
T0144	BN96-01208B	ASSY COVER P-STAND BASE;42D4,AL5052,T1.2	1
T0044	BN96-01502A	ASSY PDP P-MODULE;M3,S42SD-YD,PPS GUIDE	1
M0018	BN97-00440A	ASSY MICOM; ,D65C,29DL32,T-NELNUS-1007,20	1

MEMO