


POWER SUPPLY C.B.A. VEPS1002B2 (A,B,C) /VEPS1002D2 (D,E)

HOT CIRCUIT. BE CAREFUL AND USE AN ISOLATION TRANSFORMER WHEN SERVICING.



VJBS1002

A

B

C

D

E